

### **BACnet Success Story**:

### Central Permit Facility Libertyville, Illinois

Welcome to the Virtual Tour of the Building Automation System....

### **BACnet Success Story:** Lake County Central Permit Facility, Libertyville, IL

A green building with virtually all building systems integrated into a common BACnet Internetwork.

The "Networked Controls" plan required vendors to supply their own BACnet interface to their devices. Traditional "Stickbuilding" was minimal. Systems were networked instead.





### **BACnet Success Story:** Lake County Central Permit Facility, Libertyville, IL

Besides the BACnet Internetwork, other innovative features include a green roof and the storm water retention system.





Most systems listed below were "Networked" instead of "Stick Built". The equipment came with a BACnet interface. This simplified the installation for the BAS Contractor. It clarified responsibilities between the trades on the job. Johnson Controls integrated the lab controls together to present the system as one "BACnet device".

- 11 53 56 Lab Controls
- 🚞 14 24 00 Elevator
- 21 10 00 Pre-Action Fire Detection
- 🚞 21 10 00 Water-Based Fire Suppression
- 🚞 21 31 13 Fire Pump
- 🗀 22 11 23.13 Plumbing DW Booster Pump
- 🚞 22 13 29 Plumbing Sanitary Sewage Pumps
- 22 14 29 Plumbing Storm Pumps
- 🚞 23 21 23 HVAC Pumps
- 🗀 23 34 16 Return Fans & VSD
- 🚞 23 34 23 Exhaust Fans & VSD
- 🚞 23 36 00 VAV Boxes
- 🚞 23 52 13 Boilers Electric
- 🚞 23 52 16 Boilers Condensing

- 🚞 23 64 26 Chiller
- 🚞 23 65 00 Cooling Tower
- 🚞 23 73 13 AHUs
- 🗀 23 81 23 Data Center Cooling units
- 🚞 23 82 19 Fan Coil Units
- 🚞 23 84 13 Humidifier
- 26 09 23 Lighting Controls
- 🚞 26 14 13 Low Voltage Switchboards
- 🚞 26 32 13 EM Generator
- 🚞 28 31 00 Fire Alarm System
- 🚞 28 35 00 Refrigerant Monitor







#### Floor Position 1


Car In Normal Service Normal Car On Independent Normal Car On inspection Normal Dn Direction Pilot Normal Door Close Limit Normal Door Open Limit Normal Door Related Fault Normal Operational Fault Normal Power / comm Normal Safety Ckt Related Fault Normal Up Direction Pilot Normal Lift-Net provided a BACnet interface to the ThyssenKrupp elevator.

There are plans to expand this interface. The elevator will be monitored remotely.











The Lutron lighting panel data are shown here. The occupancy sensors are on a floor plan. HVAC uses these sensors for reducing ventilation in unoccupied rooms.

Location cmd status	Lo	ation cmd	status	Location	cmd	status	Location	cmd	status	Location	cmd	status
15a - CKT#1 🗾 Off	25w - Ck		On	10f - CKT#56		Off	20ac - CKT#78	0.	On	5 - CKT#131		On
15b - CKT#2 🗾 On	25x - Ck		Dn	12g - CKT#57		Off	22ad - CKT#79		On	7 - CKT#132	0	On
15c - CKT#3	27y - Ck	त#25 💶 🤇	Dn	12h - CKT#58		Off	32ae - CKT#80	<b>0</b> .	Off	9 - CKT#133	0 -	On
Zoomed in	view of	BACnet In	terfac	e.		Off	2c - CKT#93	<b>0</b> .	Off	11 - CKT#134	0-	On
					0]-	Off	2d - CKT#94	•••	Off	13 - CKT#135	0 -	On
Locati		l cm(	에 !!	status	0]-	Off	4e - CKT#95	<b>•</b> ••	On	15 - CKT#136	0-	On
						Off	4f - CKT#96		Off	2 - CKT#137	0	On
				-	0]-	Off	6g · CKT#97		011	4 - CKT#138	0]-	On On
│ 10f - CKT#	56I			Off	0]	Off	6h - CKT#98		Off	6 - CKT#139 8 - CKT#140	0	On
					0	On Off	8j - CKT#99 8k - CKT#100		Off	8 · CKT#140	0	On On
10. OLTH	ا به جر			<u></u>		Off Orr	8K+CKT#100 8I+CKT#101		Off Off	12 - CKT#141	0]-	On On
12q - CKT#	57	01-		Off		On Off	81+ CKT#101 81+ CKT#102		01	2a - CKT#142	0]-	On Off
					0		10m · CKT#102		Off	2b - CKT#162	<u>  -</u>	Off
12h - CKT#	5Q			Off	0]	Un On	10n · CKT#103		On On	20 - CKT#163		Off
		01-		<b>U</b>	0]	Off	120 · CKT#105	<u>•</u> ••	On	2e - CKT#164		Off
					0	Off	12p · CKT#105	<u>•</u> ••	00	4c - CKT#165		Off
– 12i - CKT#	5Q)			Off		Off	14b - CKT#107		0#	61- CKT#166		Off
	00	- 19				0.			0	54 CI/T#167		0.0
												•
12j - CKT#	50L			Off I						BACn	et	
										Internati	ona	

75.6 ⁼F 65.2 %rh	Occupancy sensors located on the floor plan.						
Basement	1st Floor Office	1st Floor Lab	2nd Floor Office	Penthouse			
	<ul> <li>17e - CKT#5</li> <li>34aj - CKT</li> <li>17f - CKT#6</li> <li>17g - CKT#7</li> <li>15a - CKT#1</li> <li>15a - CKT#1</li> <li>15b - CKT#2</li> <li>15b - CKT#2</li> </ul>	<ul> <li>◆ 19I - CKT#12</li> <li>◆ 210 - CKT#15 ◆ 21n - CKT#14</li> <li>◆ 21m - CKT#13</li> <li>◆ 21p - CKT#16</li> </ul>					



#### The Eaton Digitrip 1150 unit is on the BACnet Internetwork.

Over Temperature Normal

Phase Current Loss Normal

Ph Invers Tim Ovrcrrnt Normal Power Demand Normal

Phase Rotation Normal Ph Instant Overcurrent Normal


Over Voltage Normal

RAM Error Normal

Reset Alarm Normal

oparent Energy	61000.00	LDT GFT Faults	33.00
pparent Power	0.00	Maximum Temperature	316.39
Crest Factor Ia	0.00	Percent THD Ia	0.00
Crest Factor Ib	0.00	Percent THD Ib	0.00
Crest Factor Ic	0.00	Percent THD Ic	0.00
Crest Factor Ig	0.00	Percent THD Ig	0.00
Crest Factor In	0.00	Percent THD In	0.00
Demand la	0.00	PF Apparent	1.00
emand la Peak	0.00	PF Displacement	0.00
Demand Ib	0.00	Reactive Power	0.00
emand Ib Peak	0.00	Real Power	0.00
Demand Ic	0.00	Receive Date and Time 1	57612.00
emand Ic Peak	0.00	Receive Date and Time 2	7954.00
Event Count	111.00	Receive Date and Time 3	24.00
placeable Unit	1.00	Reverse Real Energy	0.00
rd Real Energy	59000.00	Secondary Status Code	7.00
la	0.00	Status	Open
lb	0.00	Status Reason	1.00
Ic	0.00	Status Secondary	Not Used
lg	0.00	Vab	0.00
In	0.00	Vbc	0.00
IST SDT Faults	24.00	Vca	0.00





De

De

De

IN

Reset Peak Demnd Watts Normal Earth Fault Normal 🌘 Tot Harmonic Distortion Normal Zoomed in view of

Accessory Bus Normal 🍋 Alarm Active Normal 🌘

Bad Frame Normal 🌘

Amperes Out of Balance Normal 🌘

Bad/Missing Ratng Plug Normal 🌘

Capture Waveform Normal 🌘

Discriminator Normal

Check Auxiliary Switch Normal 🌘 Communications Normal (●)


Trip Blocked Normal BACnet Interface.

Under Frequency Normal

Under Voltage Normal

Unknown Normal

VA Demand Normal



#### The GE EST Fire Alarm panel data are shown here.

- Basement Waterflow Riser 🅚
- Bsmt- Boiler Rm Heats 🌘
- Bsmt- Boiler Rm Main Vlvs 🅚
- Bsmt- Comp/Server Rm 05 East SMK 🅚
- Bsmt- Mech Rm ME02 N/E SMK

Bsmt- Mech Rm ME02 N CTR CMK 🧶

Bsmt- Mech Rm ME02 RF1 Shutdown

Zoomed in view of BACnet Interface.

Bsmt- Corr by Mech ME002 Bsmt- Corr by South Stair Pull Bsmt- Corr by West Stair Pull Bsmt- Elec Rm ME 03 East Bsmt- Elec Rm ME 03 West Bsmt- Elev Mech Rm Alternate Bsmt- Elev Mech Rm Fire Hat Bsmt- Elev Mech Rm Primary

FIr1- File Rm 1167 N SMK Damper	۲	Fir2- R
FIr1- File Rm 1167 W SMK Damper	۲	Pnthse
FIr1- N/E Exit by Rm 1234 Pull	۲	Pnthse
FIr1- Exit by Receiving Pull	۲	Pnthse
Ir1- S/E Exit by Office 1212 Pull	۲	Securi
Ir1- S Double Doors Sec. Override	۲	Smoke
Ir1- Secure Store 1230A SMK	۲	1st Flr-
Ir1- Secure Store 1230A SMK	۲	1st Fir-
Ir1- Sprinkler Rm Bsmt Riser Tmpr	۲	1st Flr
Ir1- Sprinkler Rm Fire Pump Run	۲	1st Flr-
Ir1- Sprinkler Rm FIr2 Riser Flow	۲	1st Flr-
Ir1- Sprinkler Rm FIr2 Riser Tmpr		1st Flr
Ir1- Sprinkler Rm FIr1 Riser Flow	۲	1st Flr
Ir1- Sprinkler Rm FIr1 Riser Temp	۲	1st Flr
Ir1- Sprinkler Rm Jockey Pump Valve	۲	1st Flr
Ir1- Sprinkler Rm ME1120 BPS Panel	۲	1st Flr-
Ir1- Sprinkler Rm Tamper	۲	1st Flr
Ir1- Sprinkler Rm Test Header Tmp	۲	1st Flr
Ir1- Sprinkler Rm ME1120 Knox Box	۲	1st Flr
Ir1- Sprinkler Rm Fire Pump Phase Reverse	۲	1st Flr
Ir1- Sprinkler Rm Fire Pump Power Fail	۲	1st Flr-
Ir2- Water Flow Riser Visual	۲	1st Flr
Ir2- Corr by Rm 2242 RF2 Return	۲	1st Flr
Ir2- Janitor Closet 2226 BPS Panel	۲	1st Flr





75.6 °F 65.2 %rh	Fire Alarm Devic	es located o	n the floor pla	in.
Basement	t 1st Floor Office	1st Floor Lab	2nd Floor Office	Penthouse
				S Smoke Pull DD Duct Detector SD Smoke Damper Advisory Alarm

